

New Elbe Tunnel 1, 2 and 3

Hamburg, Germany



Project Description

Due to abrasion to, and weathering of, asbestos components, the risk of asbestos dust was increased. Renovation measures were therefore put in place. As a certified specialist to TRGS 519, we removed the sprayed asbestos from the tubbing segments and replaced the fire protection materials. So as not to disrupt the motorway traffic for too long, we carried out all services in multiple shifts.

General

Company Division	Lindner Isoliertechnik &
Completion	2003 - 2011
Client	Freie Hansestadt Hamburg

© Lindner, Arnstorf (D)

© Lindner, Arnstorf (D)

© Lindner, Arnstorf (D)

© Lindner, Arnstorf (D)